



WELL CHAMBER CALIBRATION INSTRUCTIONS

Contact Wanda Kucera in Customer Service to coordinate the arrival of the well chamber and cesium-131 seed to the University of Wisconsin.

Ship Well Chamber to:

Radiation Calibration Laboratory
University of Wisconsin
1300 University Avenue
Madison, WI 53706-1532

If you do not want to send your chamber in for calibration or can not due to extenuating circumstances, you can request a seed be sent to the University for calibration and the seed will be forwarded to your facility when complete.

If you have any questions or special requests for the calibration laboratory, please contact Wendy Kennan at 608-265-9748 or wskennan@wisc.edu.

IsoRay Customer Service:

Wanda Kucera
509-375-5329 – Office Phone
509-366-4915 – Cell Phone
509-267-3670 – Fax Line
wkucera@isoray.com

